

# Excellent value for the price of the Pumpkin single din 7 inch touchscreen android car radio

## Android 10 CAR RADIO PLAYER



Ok, so I pulled the trigger on this based on price point, and the review by the guy below with the Land Rover – I have an old BMW that’s a Sunday cruiser and really just wanted to update the head unit to have Bluetooth, nothing more – for the price of a regular old Kenwood deck, I picked this up figuring the extra features, if they’re as good as promised, would be a bonus.

Unit arrived FAST, and was well packaged. Included GPS antenna, mounting bracket, a rear view camera, single din bracket and removal tools. Wiring was simple, following the schematic on the unit itself, and the notes in other reviews about making sure the blue antenna wire gets jumped to power.

Interface out of the box is good, but I chose to run a car launcher, as have some others – I like the home screen better than the stock one. App selection from the google play store is great, and there's plenty of memory to accommodate whatever you want. Even the stock offline gps is pretty solid. I'm including a few screenshots of the stock home screen, the launcher, and an app or two.

I've kicked the tires on all the features of this unit since having it and am incredibly impressed at the functionality for the price point. It performs pretty darn close to my other android units in other cars that cost much more. If you're looking for a modern single din solution for an older retrofit, or a budget friendly alternative to the Alpines, Kenwoods, and Sonys, check this out. It's a great value.

Lastly, kudos to the seller for offering EXCELLENT customer service – I expected there would be little to no support for the questions that came up about the product but was pleasantly surprised when any issues I had were resolved within a day and to my satisfaction. Five stars for a great seller who stands behind their merchandise.

See more information about [Pumpkin 7" Android 10 Single Din Bluetooth Car Stereo with Flip Screen Navigation](#).

---

# [\[Installation\] Pumpkin 7" Single Din Bluetooth Car Stereo with Flip Screen Navigation install on Volvo XC70 year 2002](#)

Here, we show how to install the 7-inch single din flip-out screen car radio in the Volvo XC70 year 2002. This is a universal car radio, it integrates with the RDS radio, Bluetooth BT hands-free calling and music streaming, GPS navigation, phone mirror-link, steering wheel control, Wi-Fi, and compatible with external USB, SD card, the Android Auto/Apple CarPlay USB Dongle, DAB+ digital radio box, OBDII car scanner device, and backup camera. The display car radio is an Android 9.0, but Pumpkin has already released the Android 10 version car radio now. You can search on the Pumpkin official website.

See more information about [Pumpkin 7" Single Din Bluetooth Car Stereo with Flip Screen Navigation](#).

---

## [Feature rich upgrade for older cars](#)

RAM  
4GB

ROM  
64GB

# Android 9.0

## CAR STEREO



I have had this [Pumpkin 7" 2 Din 8 core car radio](#) installed in my 20-year-old Focus for a couple of months now. It's double din but it seems Fords version of double din is slightly different. I had to 'modify' the dash bezel to get it to fit, that is nothing against this device.

For the most part, it's been excellent, I'm far from an expert in installing something like this but have it running with all bells and whistles (Bluetooth, wifi, backup camera, etc.). Having it display battery voltage on the main screen has been incredibly valuable to learn and understand the power consumption.

I don't believe you can use this without the engine running for too many minutes before it bleeds too much juice from the battery, having a visual display of the voltage is so useful, it could just be my car and/or battery but it should be no

surprise it's more power-hungry than what was originally intended for my car. I have yet to look into possibly a larger battery to counter/accommodate it.

The other day the screen couldn't seem to make it minds up on brightness level and flicked levels every 10 or so seconds, that hasn't happened since, but it happened.

I am suspecting my starter motor may be on it's way out as the 'instant on' feature is proving somewhat unreliable whereas initially, it worked great. Again, I have a 20-year-old car and new to this type of install, to me, there may be calculable reasons for the above and I do not believe it's this device but rather my lack of knowledge and understanding. I say this as a caution to others, maybe get a professional to install and advise!

Other than that I'm really happy with it and it's a fraction the cost of a bigger name brand with all or more features and it's Android so massive potential in customization.

As for the design, having an actual volume dial was a key factor in me choosing this, the physical Home and Back buttons have also proven superior to the touchscreen options. One tiny gripe is the black outer bezel sticks out from the screen a touch too much, so when using the touchscreen on the top edge is a tiny bit awkward, but it's not that big a deal. I'm a bit of a fiend with devices, in hindsight, I would have liked 8 gigs of RAM, again not that big a deal.

Overall I very much recommend this device.

---