

# A New Way to Use the Bluetooth of a Car Head Unit



Music streaming is the most widely and frequently used Bluetooth function in the car that installs a multimedia

player. Many car radios support Bluetooth hands-free calling and phonebook accessing, which is very handy for driving. There are other unexpected ways to use the Bluetooth music sharing function especially when you are with an enamored companion.

Music really helps tremendously if you take a serious observation, you can definitely ask this friend out again if he/ she sings and even swings with every song in your favorite playlist. Likewise, ask the friend to play her playlist via Bluetooth is a genius idea to find out what type of person is this companion, if she/he likes hip-hop, while you prefer classical music, you may need to pay some attention to other aspects of your lifestyle differences before getting involved in this relationship too deep.

Who else could think to use the Bluetooth function of a car radio in such a romantic way? (:

---

**Pumpkin AA0448B 12.8" Tesla  
Style PX6 Universal Car  
Stereo with 180 Degrees  
Adjustable Screen**

12.8"  
Touchscreen

# Android 9.0

## PUMPKIN CAR STEREO



A piece of exciting good news: Pumpkin's first Tesla Style Universal Car Stereo is available to order now. You must be expecting for a long time. 12.8 inches 180 degrees adjustable digital screen designed, the UI display interface can support the landscape and portrait display effects. The 12.8 inches 1920 \* 1080 full HD screen, which supports playback of 4K / 1080P video and offers a better watching experience. Built-in DSP sound processing 16 end EQ adjustment, supports subwoofer output, and can be adjusted separately.

Features:

OS: Android 9.0  
CPU: SIX-core CPU Processor  
RAM: DDR3 4GB  
Nand Memory: 32GB  
Screen Size: 12.8-Inch Digital Screen  
Resolution: 1920\*1080  
Bluetooth: 5.0 version  
Type: Double Din  
EQ  
GPS  
Radio  
USB  
WIFI/3G internet  
Steering Wheel Remote Control  
DAB+ Digital Radio(Extra device required)  
OBD2 (Extra device required)  
Cam-In (Extra device required)

See more information about [Pumpkin AA0448B 12.8" PX6 car stereo with 180 degrees adjustable screen.](#)

---

## [How to Troubleshoot Common Problems with a Double Din Navigation System](#)



For the high GPS navigation technology, more and more people choose to install their own [double din navigation](#) systems. Inevitably, when you run the GPS navigation system, there may be some problems. Some issues need to be resolved by Professionals, but most of problems you can resolve yourself.

## Steps

1.The GPS navigation unit doesn't start up/ could not open the GPS navigation unit.

□The key isn't turned to ACC or IGNITION position.

— Turn the vehicle key to ACC or IGNITION position.

□The power cable has not been connected to the GPS navigation unit.

— Connect the power cable to the GPS navigation unit.

□Blown fuse behind the GPS navigation unit or in the radio system.

— Replace the blown fuse with a fuse of the same amps.

□Flat battery.

— Replace or charge up the flat battery.

□The remote controller is running out of battery power.

— Change the remote control battery.

2.No sound output/could not hear voice/no voice.

- Speaker wires are not connected to the GPS navigation unit.
  - Make sure that the speaker wires are properly connected to both the GPS navigation unit and the speakers.
- The GPS navigation unit is on “Mute”.
  - Press “Mute” key or VOLUME (+/-) key.
- The volume is excessively low.
  - Press VOLUME(+) key.
- Front/Rear speaker; Left/Right speaker.
  - Press the remote control panel “OSD” or adjust the “Option” “Audio”.

3.Touch panel is not calibrated.

- Press “calibration” to calibrate the monitor again.
  - “Menu”->”Option”->”System”->”calibration”

4.No response from the touch screen.

- Possible that the system is still processing the previous task given to it.
  - If there’s still no response after a long period time, please contact the after-sale service department to have this issue looked at.

5.Can not play DVD.

- Disc loaded inaccurately.
  - Please load the disc with the graphic side showing towards the windscreen.
- Damaged disc.
  - Please clean the disc before reloading it again.
- Disc does not play at all.
  - Please check the disc format before playing it.

6.No image from the reversing camera.

- Reversing camera is installed, but it is not plugged into the [Android car stereo](#).
  - Connect the reverse camera to the double din stereo, then press the “CDD” button on the remote controller, if it still does not work, please contact your local product distributor/reseller.



7.No GPS reception.

□GPS antenna is not plugged in.

— Plug in the GPS antenna.

□No GPS reception in the current location.

— Please contact your nearest product distributor/reseller for further assistance.

Source:

[Wikihow.com](http://www.wikihow.com)

