

10off

Discount Start Date: Apr 13, 2017

Android System • Re: Feature request: Persistent radio settings

Hi,

Sorry for the late reply due to the National Day.

About the settings losing after power off and reboot, please refer another forum to check.

It's possible that the red and yellow wire to your car is reverse.

Here is the link of the latest firmware for the unit RQ0370.
Hope some help.

[https://mega.nz/#!gJNlTbwI!y_9pJo2Cuu0H ... dDQjBo8Lf8](https://mega.nz/#!gJNlTbwI!y_9pJo2Cuu0H...dDQjBo8Lf8)

Regards

Statistics: Posted by [Jammy](#) – Fri Oct 07, 2016 10:29 am

File Download • Re: S07 KC-

C0346 Issues - Need Firmware

Hi,

Sorry for the late reply due to the National Day.

If the unit even could not enter the recovery, please return it back to us for repair.

You can contact our customer service or write to "support@autopumpkin.com"

Regards

Statistics: Posted by [Jammy](#) – Fri Oct 07, 2016 10:05 am
